



Cleaner Air Oregon Permit Application

Form AQ501

LRAPA Use Only		
Permit or Source Number:	Type of Application:	
Application Number:	SIC/NAICS Code:	
Date Received:	Source Description:	
LRAPA Office: Lane County	Check No.:	Amount:

1. Permit Number:		
2. Company Information		
3. Facility Location Information		
Legal Name:		
Mailing Address:		
City:	State:	Zip Code:
Name:		
Street Address:		
City:	County:	Zip Code:
4. Facility Contact Information		
5. Facility Authorized Contact Information		
Name/Title:		
Phone:		
Email:		

6. Source Determination: *

- ☐ Existing
- ☐ New
- ☐ Exempt [OAR 340-245-0050(6)] or Gas Combustion Exemption Emissions only [OAR 340-245-0050(5)]
- ☐ De minimis [OAR 340-245-0050(7)]

7. CAO Permit Application Checklist of Approved Documents [OAR 340-245-0100(3)]:

- ☐ Source description and process flow diagrams for each process (Included in either the Modeling Protocol or Risk Assessment Work Plan)
- ☐ Emissions Inventory
- ☐ Modeling Protocol
- ☐ Risk Assessment Work Plan (for Level 3 or Level 4 Risk Assessment)
- ☐ Risk Assessment (Level 1, 2, 3 or 4)
- ☐ TBACT or TLAER supporting documentation (if applicable)
- ☐ Pollution Prevention Analysis (if applicable)
- ☐ Risk Reduction Plan (if applicable)
- ☐ Postponement of Risk Reduction (if applicable)
- ☐ Air Monitoring Plan (if applicable)
- ☐ Additional supporting documentation requested by DEQ or LRAPA
- ☐ CAO applicable Activity Fees and Annual Fee for new sources (see page 2)

8. Signature

I hereby apply for permission to discharge air contaminants in Lane County in the State of Oregon, as stated or described in any part of this application, and certify that the information contained in any part of this application and the schedules and exhibits appended hereto, are true and correct to the best of my knowledge and belief.

Name of official

Signature of official

*Applicable fees will be assessed after LRAPA receives the application. Please contact LRAPA for fee questions.

The following applicable fees will be assessed once the Cleaner Air Oregon Permit application form is received: Qty. = Number of Activities

#	ACTIVITY	Qty.	Title V	Qty.	Standard ACDP	Qty.	Simple ACDP	Qty.	General/ Basic ACDP
3	Submittal Document Modification Fee(s)		\$ 2,500		\$ 2,500		\$ 500		\$ 250
4	Level 1 Risk Assessment - de minimis (no permit required)		\$ 1,500		\$ 1,500		\$ 1,000		\$ 800
5	Level 1 Risk Assessment – not de minimis		\$ 2,000		\$ 2,000		\$ 1,500		\$ 1,100
6	Level 2 Risk Assessment - de minimis (no permit required)		\$ 3,100		\$ 3,100		\$ 2,300		\$ 2,000
7	Level 2 Risk Assessment – not de minimis		\$ 3,600		\$ 3,600		\$ 2,800		\$ 2,300
8	Level 3 Risk Assessment - de minimis (no permit required)		\$ 8,800		\$ 8,200		\$ 5,300		\$ 4,500
9	Level 3 Risk Assessment – not de minimis		\$ 19,900		\$ 11,300		\$ 7,700		\$ 6,300
10	Level 4 Risk Assessment - de minimis (no permit required)		\$ 21,400		\$ 18,500		\$ 11,700		NA
11	Level 4 Risk Assessment – not de minimis		\$ 34,600		\$ 25,800		\$ 15,500		NA
12	Risk Reduction Plan Fee		\$ 6,700		\$ 6,700		\$ 2,600		\$ 2,600
13	Air Monitoring Plan Fee (includes risk assessment)		\$ 25,900		\$ 25,900		NA		NA
14	Postponement of Risk Reduction Fee		\$ 4,400		\$ 4,400		\$ 4,400		\$ 2,000
15	TBACT/TLAER Review (per Toxic Emissions Unit and type of toxic air contaminant)		\$ 3,000		3,000		\$ 1,500		\$ 1,500
16	TEU Risk Assessment – no permit mod		\$ 1,000		\$ 1,000		\$ 500		\$ 500
17	TEU Risk Assessment – permit mod		\$ 4,000		\$ 4,000		\$ 4,000		\$ 4,000
18	Level 2 Modeling review only for TEU approval		\$ 1,900		\$ 1,300		\$ 800		\$ 700
19	Level 3 Modeling review only for TEU approval		\$ 3,800		\$ 3,800		\$ 3,500		\$ 3,500
20	Community Engagement Meeting Fee – high		\$ 8,000		\$ 8,000		\$ 8,000		\$ 8,000
21	Community Engagement Meeting Fee – medium		\$ 4,000		\$ 4,000		\$ 4,000		\$ 4,000
22	Community Engagement Meeting Fee - low		\$ 1,000		\$ 1,000		\$ 1,000		\$ 1,000
23	Source Test Review Fee (plan and data review) - complex		\$ 6,000		\$ 6,000		\$ 6,000		\$ 6,000
24	Source Test Review Fee (plan and data review) – moderate		\$ 4,200		\$ 4,200		\$ 4,200		\$ 4,200
25	Source Test Review Fee (plan and data review) - simple		\$ 1,400		\$ 1,400		\$ 1,400		\$ 1,400

Total Fees:	
--------------------	--

**An invoice will be issued once the forms are received by LRAPA.
Send payment to:**

Lane Regional Air Protection Agency (LRAPA)
1010 Main Street
Springfield, OR 97477