

NEW/OPEN ENFORCEMENT ACTIONS DETAIL REPORT
06/01/2026 – 06/30/2026
Report of open actions initiated since last report

NEW (Enforcement actions issued in the current reporting period:

1. HEATHER OAK WOOD PRODUCTS (EUGENE)
 - A. Violation: Allowed particulate matter to become airborne and travel outside the property boundary to surrounding residences and businesses and is in violation of Conditions 2.4 & 2.5 LRAPA issued ACDP permit 201289.
 - B. Initial Action Taken: NON #3945 issued 06/10/2026
 - C. Subsequent Action: NCP #2025-3945 (\$1,800) issued 06/10/2026 - paid
 - D. Resolution: CASE CLOSED on 06/29/2026
 - E. Source Type: ACDP
 - F. Initiated By: COMPLAINT AND INSPECTION
2. SWANSON GROUP MFG. LLC (SPRINGFIELD)
 - A. Violation: Respondent had six (6) excess emission events in reporting year 2024 and two (2) excess emissions events in reporting year 2025. All events, but the event on 1/11/2024, were reported in their semi-annual reports for the 2024 & 2025 reporting periods.
 - B. Initial Action Taken: NON #3960 issued 06/30/2026
 - C. Subsequent Action: NCP #2026-3960 (\$22,200) issued 06/30/2026
 - D. Resolution: PENDING
 - E. Source Type: TITLE V
 - F. Initiated By: INSPECTION AND REPORTING
3. JANICE CASTLE & JEFFREY HEITZMAN (EUGENE)
 - A. Violation: Outdoor burning of prohibited materials (plywood and treated lumber wrapped in metal fasteners)
 - B. Initial Action Taken: NON #3963 issued 06/23/2026

- C. Subsequent Action: NCP #2026-3963 (\$8,088) issued 06/23/2026
 - D. Resolution: PENDING
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
4. ALPINE ABATEMENT ASSOC., INC. (EUGENE)
- A. Violation: During an asbestos abatement inspection, LRAPA observed the following violations of LRAPA Title 43 - Asbestos Requirements of interim storage location for waste was left unsecured and unlabeled; negative pressure enclosures did not have viewing windows installed to allow for observation of the abatement area; did not maintain a proper NPE during the project. Containment was cut open during abatement to install a viewing window.
 - B. Initial Action Taken: NON #3965 issued 06/23/2026
 - C. Subsequent Action: NCP #2026-3965 (\$19,200) issued 06/23/2026
 - D. Resolution: PENDING
 - E. Source Type: ASBESTOS
 - F. Initiated By: INSPECTION
5. EDWARD LITTEN (NOTI)
- A. Violation: Outdoor burning of prohibited materials, burned at night outside of allowed outdoor burning times as set by LRAPA outdoor burning advisory, and burned construction and demolition debris without an Outdoor burning Letter issued permit.
 - B. Initial Action Taken: NON #3967 issued 06/23/2026
 - C. Subsequent Action: NCP #2026-3967 (\$3,850) issued 06/23/2026
 - D. Resolution: PENDING
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
6. ROSE CITY CONTRACTING (SPRINGFIELD)
- A. A. Violation: Respondent failed to employ a compliant negative pressure enclosure as required under 43-015-11.F(4); failed to install viewing windows in the

enclosures as required under 43-015-11.F(5)(a); failed to affix required asbestos warning labels to enclosure and mobile storage cart as required under 43-015-11.H. Additionally, no prior written Agency approval was obtained for the use of an alternative to the negative pressure enclosure requirement in violation of 43-015-11.U.

- B. Initial Action Taken: NON #3972 issued 06/16/2026
 - B. C. Subsequent Action: PENDING
 - D. Resolution: PENDING
 - E. Source Type: ASBESTOS
 - F. Initiated By: INSPECTION
7. JERRY NELSON (CRESWELL)
- A. Violation: Outdoor burning of prohibited materials (dimensional lumber, plywood /pressboard, tires, and household garbage).
 - B. Initial Action Taken: NON #3973 issued 06/22/2026
 - C. Subsequent Action: PENDING
 - D. Resolution: PENDING
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
8. SFPP, L.P. EUGENE TERMINAL (EUGENE)
- A. Violation: Respondent did not submit Internal Floating Roof seal inspection reports and External Floating Roof gap seal inspections and measurements in a timely manner for the 2025 reporting year, required under 40 CFR part 60 subpart Kb according to Condition 20 of Title V Operating Permit 207506. Additionally, notification of the External Floating Roof inspection was not submitted in a timely manner for the 2025 annual reporting year. This is a report required under 40 CFR part 63 subpart WW according to Condition 30. These are both violations of Title V Permit 207506 Conditions 82.a.v and 82.a.vi.
 - B. Initial Action Taken: NON #3975 issued 06/15/2026
 - C. Subsequent Action: PENDING
 - D. Resolution: PENDING

- E. Source Type: TITLE V
 - F. Initiated By: INSPECTION AND REPORTING
9. BRINK'S LAND IMPROVEMENT (BLUE RIVER)
- A. Violation: Submitted incomplete 5-Day Notification and fees to abate non-friable asbestos-containing transite pipe, located on 'Route 126' near or at Blue River, Oregon; failure to provide address or specific location and fees and request for emergency waiver of the 5-day non-friable asbestos abatement requirement, prior to commencing work on 6/15/2026.
 - B. Initial Action Taken: NON #3976 issued 06/15/2026
 - C. Subsequent Action: PENDING
 - D. Resolution: PENDING
 - E. Source Type: ASBESTOS
 - F. Initiated By: COMPLAINT

PENDING (Enforcement actions issued prior to 06/01/2026 with subsequent action in the current reporting period):

1. RADIUS RECYCLING (EUGENE)
- A. Violation: Outdoor burning where prohibited and outdoor burning of prohibited materials.
 - B. Initial Action Taken: NON #3951 issued 1/14/2026
 - C. Subsequent Action: NCP #2025-3951 (\$26,435) issued 06/30/2026
 - D. Resolution: PENDING
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT

PENDING (Enforcement actions issued prior to 06/01/2026 with no reporting action in the current reporting period):

1. JEFFREY HEITZMAN & JANICE CASTLE (EUGENE)

- A. Violation: Outdoor burning of prohibited materials including construction/ demolition debris.
 - B. Initial Action Taken: NON #3948 issued 1/15/2026
 - C. Subsequent Action: NCP #2025-3948 (\$3,388) issued 1/15/2026; no response, default order and judgment (DOJ) in process.
 - D. Resolution: PENDING
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
2. GREENSIDE CONSTRUCTION INC. (HAPPY VALLEY)
- A. Violation: During an inspection, no signage identifying an air curtain incinerator activities and information was present at Buford Park in Eugene which is in violation of their Permit No. 206131 condition 6.1.c. ii.
 - B. Initial Action Taken: NON #3953 issued 1/27/2026
 - C. Subsequent Action: PENDING – waiting for additional information due 3/15/2026; no additional information received.
 - D. Resolution: PENDING
 - E. Source Type: ACI
 - F. Initiated By: INSPECTION
3. DUST 2 DIAMONDS, LLC (SPRINGFIELD)
- A. A. Violation: Performed an asbestos abatement project without possessing a license to perform asbestos abatement; openly accumulated friable asbestos-containing materials.
 - B. Initial Action Taken: NON #3908 issued 9/6/2024
 - C. Subsequent Action: NCP #2024-3908 (\$8,400) issued 9/6/2024; request for reduction approved and reduced to \$4,800 with a payment plan of \$100; payment was not received, a default order and judgment (DOJ) in process.
 - D. Resolution: PENDING
 - E. Source Type: ASBESTOS

- F. Initiated By: INSPECTION
4. REMEDIOS ROMERO (COTTAGE GROVE)
- A. Violation: Respondent conducted the burning of prohibited materials, including painted wood, metal, tin cans, plastic bags, food waste, plastics fiberglass roofing and general household garbage in a burn barrel.
 - B. Initial Action Taken: NON #3930 issued 08/06/2025
 - C. Subsequent Action: NCP #2025-3930 (\$1,019) issued 08/06/2025; no response, default order and judgment (DOJ) in process.
 - D. Resolution: PENDING
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
5. LANE FOREST PRODUCTS (EUGENE)
- A. Violation: Lane Forest Products has not been conducting the required monthly fugitive emission surveys as outlined in ACDP 204741 Permit Condition 12 of their current permit (issue date 6/4/2024) which is the required monitoring component of preventing excess emissions of particulate matter.
 - B. Initial Action Taken: NON #3950 issued 04/13/2026
 - C. Subsequent Action: PENDING
 - D. Resolution: PENDING
 - E. Source Type: ACDP
 - F. Initiated By: COMPLAINT

CLOSED ENFORCEMENT CASES Enforcement closed in the current reporting period 06/01/2026 – 06/30/2026):

1. MANELLA PROPERTIES, LLC (EUGENE)
- A. Violation: It is alleged that the rental property management and tenants allowed for the burning of prohibited materials (treated wood and dimensional lumber).
 - B. Initial Action Taken: NON #3962 issued 5/13/2026

- C. Subsequent Action: None.
 - D. Resolution: CASE CLOSED 6/13/2026
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
2. MERCEDES LEWIS (JUNCTION CITY)
- A. Violation: Outdoor burning of prohibited materials.
 - B. Initial Action Taken: NON #3964 issued 5/13/2026
 - C. Subsequent Action: None.
 - D. Resolution: CASE CLOSED 6/1/2026
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
3. RICHARD FLYNN (EUGENE)
- A. Violation: Outdoor burning of prohibited materials.
 - B. Initial Action Taken: NON #3966 issued 5/13/2026
 - C. Subsequent Action: None.
 - D. Resolution: CASE CLOSED 6/1/2026
 - E. Source Type: OUTDOOR BURNING
 - F. Initiated By: COMPLAINT
4. HEXION INC. (SPRINGFIELD)
- A. Violation: It is alleged that Hexion did not monitor or report PSELs, HAP PSELs or Production/Usage process parameters on a 12-month rolling basis for the reporting year 2025 required by ACDP 200510. Additionally, due to not monitoring on a 12-month rolling basis, Boiler 1 (Johston) Exhaust Bypass and RTU Dry Material Loading limits were exceeded for the 2025 reporting year.
 - B. Initial Action Taken: NON #3968 issued 5/13/2026

- C. Subsequent Action: Hexion submitted documents and plan to mitigate this from continuing by submitting an application to modify their ACDP permit.
 - D. Resolution: CASE CLOSED 6/1/2026
 - E. Source Type: ACDP
 - F. Initiated By: INSPECTION AND REPORTING
5. ENVIRONMEX CONTRACTING INC. (EUGENE)
- A. Violation: Performed an asbestos abatement project without installing a full negative pressure enclosure around the abatement area.
 - B. Initial Action Taken: NON #3970 issued 5/21/2026
 - C. Subsequent Action: None.
 - D. Resolution: CASE CLOSED 6/1/2026
 - E. Source Type: ASBESTOS
 - F. Initiated By: INSPECTION